


Handling and storage.




Before you start. PPE required: hard hat, eye protection, gloves, steel-toe boots. Everyone handling or unloading must read and understand these instructions first.

Handling



1 Keep the straps on.

Do not remove straps from pallets until they are safely stored and secured. Windows may fall. Exercise caution.



2 Never catch a falling window.


Do not try to catch a window if it falls.

Storage



3 Upright, on their supports.

Keep windows upright to prevent unnecessary pressure. **Do not** stack windows directly on the ground or on top of one another. Always store windows on the transport supports they came on.



4 Indoors, out of the weather.

Store windows indoors or in a covered area, with airflow. Keep them out of rain, strong wind and extreme temperatures. Protect them from direct sunlight and excessive heat.